

Reference	di	ds	Reference	di	ds	Reference	di	ds	Reference	di	ds
0380-35	38	3,50	0980-35	98	3,50	0620-40	62	4,00	0270-50	27	5,00
0390-35	39		0990-35	99		0630-40	63		0280-50	28	
0400-35	40		1000-35	100		0640-40	64		0290-50	29	
0410-35	41		0050-40	5	0650-40	65	0300-50		30		
0420-35	42		0060-40	6	0660-40	66	0310-50		31		
0430-35	43		0070-40	7	0670-40	67	0320-50		32		
0440-35	44		0080-40	8	0680-40	68	0330-50		33		
0450-35	45		0090-40	9	0690-40	69	0340-50		34		
0460-35	46		0100-40	10	0700-40	70	0350-50		35		
0470-35	47		0110-40	11	0710-40	71	0360-50		36		
0480-35	48		0120-40	12	0720-40	72	0370-50		37		
0490-35	49		0130-40	13	0730-40	73	0380-50		38		
0500-35	50		0140-40	14	0740-40	74	0390-50		39		
0510-35	51		0150-40	15	0750-40	75	0400-50		40		
0520-35	52		0160-40	16	0760-40	76	0410-50		41		
0530-35	53		0170-40	17	0770-40	77	0420-50		42		
0540-35	54		0180-40	18	0780-40	78	0430-50		43		
0550-35	55		0190-40	19	0790-40	79	0440-50		44		
0560-35	56		0200-40	20	0800-40	80	0450-50		45		
0570-35	57		0210-40	21	0810-40	81	0460-50		46		
0580-35	58		0220-40	22	0820-40	82	0470-50		47		
0590-35	59		0230-40	23	0830-40	83	0480-50		48		
0600-35	60		0240-40	24	0840-40	84	0490-50		49		
0610-35	61		0250-40	25	0850-40	85	0500-50		50		
0620-35	62		0260-40	26	0860-40	86	0510-50		51		
0630-35	63		0270-40	27	0870-40	87	0520-50		52		
0640-35	64		0280-40	28	0880-40	88	0530-50		53		
0650-35	65		0290-40	29	0890-40	89	0540-50		54		
0660-35	66		0300-40	30	0900-40	90	0550-50		55		
0670-35	67		0310-40	31	0910-40	91	0560-50		56		
0680-35	68		0320-40	32	0920-40	92	0570-50		57		
0690-35	69		0330-40	33	0930-40	93	0580-50		58		
0700-35	70		0340-40	34	0940-40	94	0590-50		59		
0710-35	71		0350-40	35	0950-40	95	0600-50		60		
0720-35	72		0360-40	36	0960-40	96	0610-50		61		
0730-35	73	0370-40	37	0970-40	97	0620-50	62				
0740-35	74	0380-40	38	0980-40	98	0630-50	63				
0750-35	75	0390-40	39	0990-40	99	0640-50	64				
0760-35	76	0400-40	40	1000-40	100	0650-50	65				
0770-35	77	0410-40	41	0060-50	6	0660-50	66				
0780-35	78	0420-40	42	0070-50	7	0670-50	67				
0790-35	79	0430-40	43	0080-50	8	0680-50	68				
0800-35	80	0440-40	44	0090-50	9	0690-50	69				
0810-35	81	0450-40	45	0100-50	10	0700-50	70				
0820-35	82	0460-40	46	0110-50	11	0710-50	71				
0830-35	83	0470-40	47	0120-50	12	0720-50	72				
0840-35	84	0480-40	48	0130-50	13	0730-50	73				
0850-35	85	0490-40	49	0140-50	14	0740-50	74				
0860-35	86	0500-40	50	0150-50	15	0750-50	75				
0870-35	87	0510-40	51	0160-50	16	0760-50	76				
0880-35	88	0520-40	52	0170-50	17	0770-50	77				
0890-35	89	0530-40	53	0180-50	18	0780-50	78				
0900-35	90	0540-40	54	0190-50	19	0790-50	79				
0910-35	91	0550-40	55	0200-50	20	0800-50	80				
0920-35	92	0560-40	56	0210-50	21	0810-50	81				
0930-35	93	0570-40	57	0220-50	22	0820-50	82				
0940-35	94	0580-40	58	0230-50	23	0830-50	83				
0950-35	95	0590-40	59	0240-50	24	0840-50	84				
0960-35	96	0600-40	60	0250-50	25	0850-50	85				
0970-35	97	0610-40	61	0260-50	26	0860-50	86				